

APPENDIX A
SITE PHOTOGRAPHS

PHOTO POINTS – REACH #1



Photo Point #1. Facing upstream Year 2005



Photo Point #1. Facing downstream Year 2005



Photo Point #2. Facing Upstream – Year 2005



Photo Point #2. Facing downstream – Year 2005



Photo Point #3. Facing upstream – Year 2005



Photo Point #3. Facing downstream – Year 2005



Overview of Reach #1. Facing upstream – Year 2005



Facing upstream from culvert at end of Reach #1 – Year 2005

PHOTO POINTS – REACH #2



Photo Point #4. Facing upstream – Year 2005



Photo Point #4. Facing downstream – Year 2005



Photo Point #5. Facing upstream – Year 2005



Photo Point #5. Facing downstream – Year 2005



Photo Point #6. Facing upstream – Year 2005



Photo Point #6. Facing downstream – Year 2005



Overview of Reach #2. Facing upstream – Year 2005



Overview of Reach #2. Facing downstream – Year 2005

Potential Problem Areas



Localized bank scour along Reach #2 at Station 5+18 – Year 2005